

| | |
|-----|---------|
| Ax1 | Fx1 |
| Bx1 | Gx1 |
| Cx1 | Hx5 |
| R | L |
| Dx1 | Ix12 |
| Ex1 | Kx1 |
| | M6*20mm |
| | Jx8 |

1.

3.

5.

make sure all screws are placing in the middle of the screw holes before tightening them.

2.

4.

make sure all screws are placing in the middle of the screw holes before tightening them.

6.